

Annexure D

BUILDING SAFETY CERTIFICATE

No. 169/2026-27

Date:29.04.2026

It is certified that the existing building Ocean Global School, (Name of the building or premises) at Jeppinamogaru Mangaluru Dakshina Kannada (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground+4					

The building is owned/occupied by Ocean Global School, Jeppinamogaru, Mangaluru Dakshina Kannada District (name of the Institution) have complied with the Building stability requirements and verified by the officers concerned of Public Works Department (Name of Department/Govt.) on 22.04.2026 (Date of Inspection) in the presence of The Principal, Ocean Global School, Jeppinamogaru, Mangaluru Dakshina Kannada District (Name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 29.04.2026 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.


1. Building to be maintained Periodically.

- 2.
- 3.
- 4.

Issued on 29.04.2026 at Mangaluru by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


ASSISTANT ENGINEER
P.W.D No. 1 Sub Division
Mangaluru

Signature with Seal: 
Assistant Executive Engineer
Public Works, Department
No. 1 Sub - Division Mangaluru
Designation: _____

Name & Address of Department/Office: _____

